


In this project, the material is a fairly tough H13 steel. The machining requires two holes and two slots that cross each other, with a tolerance. Make a complete program to machine the holes and slots.



➡ To develop the part program, follow these conditions:

1. Use  $\varnothing 1.0$  spot drill to make a  $0.02 \times 45^\circ$  chamfer
2. Drill the two holes to 1.25 full depth
3. Tap the two holes 1/2-13
4. Use  $\varnothing 5/8$  roughing end mill with a  $0.06 \times 45^\circ$  corner built-in
5. Use  $\varnothing 5/8$  finishing end mill with a  $0.06 \times 45^\circ$  corner built-in
6. Program nominal drawing sizes - **not mid-tolerances** !

**Answer this question:**

**Based on the drawing tolerances, how many offsets are required for finishing?  
Explain why.**