

## (43-02 - SCALING EXERCISE)

## (MAIN PROGRAM)

(T01 = 20 MM DIA END MILL)

```

N1 G21
N2 G50                                (SCALING OFF)
N3 G17 G40 G80 T01
N4 M06
N5 G90 G54 G00 X95.0 Y37.5 S2500 M03 (CONTOUR START POINT)
N6 G43 Z3.0 H01 M08
N7 G01 Z-3.0 F300.0                  (DEPTH OF THE SMALLEST CONTOUR)
N8 G51 I37.5 J37.5 P0.5              (SCALING DATA - 0.5 SCALE)
N9 M98 P4352                         (SCALED CONTOUR CUTTING)
N10 G01 Z-5.9                        (DEPTH OF THE MIDDLE CONTOUR)
N11 G51 I37.5 J37.5 P0.7             (SCALING DATA - 0.7 SCALE)
N12 M98 P4352                       (SCALED CONTOUR CUTTING)
N13 G01 Z-8.5                       (DEPTH OF THE LARGEST CONTOUR)
N14 G51 I37.5 J37.5 P0.9            (SCALING DATA - 0.9 SCALE)
N15 M98 P4352                       (SCALED CONTOUR CUTTING)
N16 M09
N17 G28 Z3.0 M05
N18 G50                                (SCALING OFF - REPEATED FOR SAFETY)
N19 G00 X-50.0 Y250.0              (PART CHANGE POSITION)
N20 M30
%
```

## O4352 (SUB FOR 43-02 SCALING EXERCISE)

(D51 = CUTTER RADIUS = 10 MM)

```

N101 G01 G41 Y57.5 D51              (LEAD-IN LINE WITH G41)
N102 G03 X75.0 Y37.7 I0 J-20.0 F250.0 (LEAD-IN ARC)
N103 G01 Y10.0
N104 G02 X65.0 Y0 I-10.0 J0
N105 G01 X10.0
N106 G02 X0Y10.0 I0 J10.0
N107 G01 Y65.0
N108 G02 X10.0 Y75.0 I10.0 J0
N109 G01 X65.0
N110 G02 X75.0 Y65.0 I0 J-10.0
N111 G01 Y37.5
N112 G03 X95.0 Y17.5 I20.0 J0        (LEAD-OUT ARC)
N113 G00 G40 Y37.5 F500.0           (LEAD-OUT LINE WITH G40)
N114 G50                            (SCALING OFF)
N115 X95.0 Y37.5                    (RETURN TO ORIGINAL START - NOT SCALED)
N116 M99
%
```