

Peter Smid	CAD/CAM Lathe	CNC lathe programming and machining exercise Facing - Turning - Undercut - Threading - Part-off	3 : 1 TURNING EXAMPLE