

➡ In this project, the only objective is to apply multiple work offsets:

1. In the illustration below, use leader lines (lines with a single arrow) to identify work offsets for all three parts loaded on the same machine table. Only one arrow per line is required, showing the direction of measurement.

