

Peter Smid	CAD/CAM Lathe	Contour change points - lathe application Identified in Autocad by XZ.LSP utility	1.5 : 1 CANDLE HOLDER 3 ENDPOINTS