

Peter Smid	CNC BASIC	Basic Programming Example Spot Drill - Drill - Tap	26-02s 4 Metric Holes - SU